

AUG 2.4 2009

CofC

1000 Eagle Gate Tower, 60 East South Temple | Salt Lake City, Utah 84111 Tel: (801) 533-9800 | Fax: (801) 328-1707 | www.wnlaw.com

PATENT Docket No. 16073.1

Art Unit

3617

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of

Ernest Bruce Durbano

Serial No.:

10/798,052

Filed:

Mar. 10, 2004

Confirmation No.:

4955

For:

RAILROAD PANEL PLACEMENT SYSTEM

Examiners:

S. Joseph Morano and Robert J. McCarry, Jr.

Patent No.:

7,287,476 B2

Issue Date:

Oct. 30, 2007

REQUEST FOR A CERTIFICATE OF CORRECTION UNDER 37 C.F.R. § 1.323

Attention: Certificate of Corrections Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Certificate

AUG 2 6 2009

of Correction

Dear Commissioner:

In accordance with the provisions of 37 C.F.R. § 1.323, which implements 35 U.S.C. § 255, the Director is respectfully requested to issue a Certificate of Correction to correct mistakes in the above-identified patent. The enclosed Patent Office Form PTO/SB/44 reflects the desired corrections.

Payment in the amount of \$100.00 as set forth in 37 C.F.R. § 1.20(a) is submitted herewith to cover the costs for issuance of the requested Certificate of Correction. The Commissioner is hereby authorized to charge payment of any of the following fees that may be applicable to this communication, or credit any overpayment, to Deposit Account No. 23-3178: (1) any filing fees required under 37 CFR § 1.16; (2) any patent application and reexamination processing fees under 37 CFR § 1.17; and/or (3) any post issuance fees under 37 CFR § 1.20. In addition, if any additional extension of time is required, which has not otherwise been requested,

please consider this a petition therefore and charge any additional fees that may be required to Deposit Account No. 23-3178.

Dated this MM day of MM 1009

Respectfully submitted,

Michael G. Pate

Attorney for Applicant Registration No.: 53,439

WORKMAN NYDEGGER 1000 Eagle Gate Tower 60 East South Temple Salt Lake City, UT 84111

Phone: 801-533-9800 Fax: 801-328-1707

MGP:ftm Enclosures 2232233v1

CERTIFICATE OF DEPOSIT UNDER 37 C.F.R. § 1.8

Respectfully submitted,

Transmitted:

REQUEST FOR A CERTIFICATE OF CORRECTION UNDER 37 C.F.R. § 1.323 PTO Form PTO/SB/44 and check no. 100 in the amount of \$100.00.



1000 Eagle Gate Tower, 60 East South Temple | Sait Lake City, Utah 84111 Tel: (801) 533-9800 | Fax: (801) 328-1707 | www.wnlaw.com



PATENT Docket No. 16073.1

Art Unit

3617

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of

Ernest Bruce Durbano

Serial No.:

10/798,052

Filed:

Mar. 10, 2004

Confirmation No.:

4955

For:

RAILROAD PANEL PLACEMENT SYSTEM

Examiners:

S. Joseph Morano and Robert J. McCarry, Jr.

Patent No.:

7,287,476 B2

Issue Date:

Oct. 30, 2007

REQUEST FOR A CERTIFICATE OF CORRECTION UNDER 37 C.F.R. § 1.323

Attention: Certificate of Corrections Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Dear Commissioner:

In accordance with the provisions of 37 C.F.R. § 1.323, which implements 35 U.S.C. § 255, the Director is respectfully requested to issue a Certificate of Correction to correct mistakes in the above-identified patent. The enclosed Patent Office Form PTO/SB/44 reflects the desired corrections.

Payment in the amount of \$100.00 as set forth in 37 C.F.R. § 1.20(a) is submitted herewith to cover the costs for issuance of the requested Certificate of Correction. The Commissioner is hereby authorized to charge payment of any of the following fees that may be applicable to this communication, or credit any overpayment, to Deposit Account No. 23-3178: (1) any filing fees required under 37 CFR § 1.16; (2) any patent application and reexamination processing fees under 37 CFR § 1.17; and/or (3) any post issuance fees under 37 CFR § 1.20. In addition, if any additional extension of time is required, which has not otherwise been requested.

please consider this a petition therefore and charge any additional fees that may be required to Deposit Account No. 23-3178.

Dated this 104 day of 11111 day of 11111 day.

Respectfully submitted,

Michael G. Pate

Attorney for Applicant Registration No.: 53,439

WORKMAN NYDEGGER 1000 Eagle Gate Tower 60 East South Temple Salt Lake City, UT 84111 Phone: 801-533-9800

Fax: 801-328-1707

MGP:ftm Enclosures 2232233v1

CERTIFICATE OF DEPOSIT UNDER 37 C.F.R. § 1.8

Respectfully submitted,

Transmitted:

REQUEST FOR A CERTIFICATE OF CORRECTION UNDER 37 C.F.R. § 1.323 PTO Form PTO/SB/44 and check no. in the amount of \$100.00.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page _ 1_ of _ 3_

PATENT NO.

7,287,476 B2

APPLICATION NO.:

10/798,052

ISSUE DATE

Oct. 30, 2007

INVENTOR(S)

Ernest Bruce Durbano

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 3

Line 47, change "II" to --H--

Column 5

Line 30, change "114" to --112--Line 30, change "130" to --128--

Column 6

Line 7, change "210" to --211--Line 63 change "172" to --170--Line 66 change "170" to --172--

Column 10

Line 32, change "farther" to --further--

MAILING ADDRESS OF SENDER (Please do not use customer number)
Michael G. Pate, Esq.
WORKMAN NYDEGGER
1000 Eagle Gate Tower
60 East South Temple
Salt Lake City, Utah 84111

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page _2_ of _3_

PATENT NO.

7,287,476 B2

APPLICATION NO.:

10/798,052

ISSUE DATE

Oct. 30, 2007


INVENTOR(S)

Ernest Bruce Durbano

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 6, replace Fig. 6 with the figure depicted herein below, wherein the second instance of reference "210" to the rack and pinion gear has been changed to --211--



MAILING ADDRESS OF SENDER (Please do not use customer number) Michael G. Pate, Esq. WORKMAN NYDEGGER 1000 Eagle Gate Tower 60 East South Temple Salt Lake City, Utah 84111

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page _3_ of _3_

PATENT NO.

7,287,476 B2

APPLICATION NO.:

10/798,052

ISSUE DATE

Oct. 30, 2007


INVENTOR(S)

Ernest Bruce Durbano

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 7, replace Fig. 6a with the figure depicted herein below, wherein the second instance of reference "210" to the rack and pinion gear has been changed to -211--



MAILING ADDRESS OF SENDER (Please do not use customer number)
Michael G. Pate, Esq.
WORKMAN NYDEGGER
1000 Eagle Gate Tower
60 East South Temple
Salt Lake City, Utah 84111

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page _ 1 _ of _ 3

PATENT NO.

7,287,476 B2

APPLICATION NO.:

10/798,052

ISSUE DATE

Oct. 30, 2007

INVENTOR(S)

Ernest Bruce Durbano

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 3

Line 47, change "II" to -H-

Column 5

Line 30, change "114" to -112--Line 30, change "130" to -128--

Column 6

Line 7, change "210" to --211--Line 63 change "172" to --170--Line 66 change "170" to --172--

Column 10

Line 32, change "farther" to -further-

MAILING ADDRESS OF SENDER (Please do not use customer number)
Michael G. Pate, Esq.
WORKMAN NYDEGGER
1000 Eagle Gate Tower
60 East South Temple
Salt Lake City, Utah 84111

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTC-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page _2_ of _3

PATENT NO.

7,287,476 B2

APPLICATION NO.:

10/798,052

ISSUE DATE

Oct. 30, 2007


INVENTOR(S)

Ernest Bruce Durbano

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 6, replace Fig. 6 with the figure depicted herein below, wherein the second instance of reference "210" to the rack and pinion gear has been changed to --211--



MAILING ADDRESS OF SENDER (Please do not use customer number)
Michael G. Pate, Esq.
WORKMAN NYDEGGER
1000 Eagle Gate Tower
60 East South Temple
Salt Lake City, Utah 84111

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page <u>3</u> of <u>3</u>

PATENT NO.

7,287,476 B2

APPLICATION NO.:

10/798,052

ISSUE DATE

Oct. 30, 2007


INVENTOR(S)

Ernest Bruce Durbano

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 7, replace Fig. 6a with the figure depicted herein below, wherein the second instance of reference "210" to the rack and pinion gear has been changed to --211--



MAILING ADDRESS OF SENDER (Please do not use customer number)
Michael G. Pate, Esq.
WORKMAN NYDEGGER
1000 Eagle Gate Tower
60 East South Temple
Salt Lake City, Utah 84111